



The October 2019 Cotabato Earthquake Sequence: Parameters and impacts

Jeffrey S. Perez

DOST-PHIVOLCS Quick Response Team

DOST-PHIVOLCS Quick Response Team

Department of Science and Technology – Philippine Institute of Volcanology and Seismology

Jeffrey S. Perez

Maria Isabel T. Abigania

Miguel Florido G. Abitang

Ranier G. Amilbahar

Ericson B. Bariso

Manolito P. Begonia

Hermes V. Daquipa

June Rostom A. Danganan

Margarita P. Dizon

Dave Benedict B. Emerenciana

Flenson Jay C. Gallardo

Giovy F. Ganipan

Florinette B. Garcia

Alvin T. Garil

Robinson F. Jorgio

Eduardo T. Lauron

Deo Carlo E. Llamas

Robjunelieaaa B. Lim

Margarita Andrea P. Mahor

Gerald A. Malipot

Fatima M. Moncada

Kathleen L. Papiona

Ron Stephen D. Pitapit

Roderick D. Ramos



Antonella B. Rosana

Milo S. Tabigue

John Harold B. Tabuzo

Nathan Azriel S. Veracruz






Active and Potentially Active Faults (AO 19 November 1994)
Maximum credible earthquake magnitudes were computed using the Magnitude Scaling Relationship by Wells and Coppersmith (1994)

The October 2019 Series of Earthquakes in Cotabato and Vicinity


Summary

In October 2019, a series of strong shallow earthquakes struck the province of Cotabato and vicinity. These earthquakes occurred on October 16, 7:37 PM Philippine Standard Time (PST) at magnitude 6.3, on October 29, 9:04 AM and 10:42 AM at magnitudes 6.6 and 6.1, respectively, and on October 31, 9:11 AM at magnitude 6.5. The depths of these earthquakes range from 7 to 9 km. Initial information on the hypocenters of the earthquakes and their focal mechanism solutions suggest that they are generated by the Cotabato Fault System, a system of strike-slip faults transecting the provinces of Cotabato, Davao del Sur, Maguindanao, Sarangani, South Cotabato, and Sultan Kudarat. Due to the quick succession of these events, damages to structures were severe and widespread. Geologic impacts, especially landslides, were also numerous.

The DOST-PHIVOLCS Quick Response Team (QRT) was immediately deployed on 18 October 2019 and 30 October 2019 to: 1) conduct earthquake information dissemination and education for local government units (LGUs) and locals in the affected areas; 2) conduct field surveys to determine the earthquakes' geologic impacts and effects to structures; 3) deploy temporary seismic stations for continuous aftershocks monitoring; and 4) assist the LGUs, together with the Mines and Geosciences Bureau, in assessing selected evacuation/relocation sites in terms of earthquake hazards. Based on field investigations, the geologic impacts included numerous tension cracks and earthquake-induced landslides, especially near the epicentral region in Makilala, Kidapawan City, and Tulunan in Cotabato; and in Magsaysay and Bansalan in Davao del Sur. Liquefaction was manifested by lateral spreading, sandboils, sandblows, road buckling, ground undulation, and subsidence in low-lying and water-saturated areas of M'lang, Kabacan, Pikit, Tulunan, Makilala, and Magpet in Cotabato; Hagonoy, Magsaysay, Matanao, Digos City, Malalag, and Padada in Davao del Sur; and Paggawan, Maguindanao. Moreover, locations of landslides and severe damage to structures after the October 31, M6.5 earthquake follow a northeast-trend and are concentrated on the central portion of Makilala and eastern portion of Kidapawan City, Cotabato where, based on the PHIVOLCS Earthquake Intensity Scale (PEIS), Intensity VIII (Very Destructive) was observed. Other damage to structures and other geologic impacts (e.g. liquefaction and tension cracks) were observed in areas where the intensity was either PEIS VII (Destructive) or PEIS VI (Strong). Poor engineering and the use of substandard construction materials were the major contributing factors to the damages.



The histogram (A) and map (B) above illustrate the respective time frequency and spatial distribution of the series of earthquakes. The spikes in daily earthquake count show that the M6.3, M6.6, and M6.5 earthquakes are separate events. These main events' Centroid-Moment-Tensor (CMT) solutions (C) show similar predominantly strike-slip mechanisms of the earthquakes. Subsequent smaller-magnitude earthquakes are aftershocks which decay through time. While the M6.3 aftershocks follow the normal decaying trend, the occurrence of the M6.6, M6.1, and M6.5 earthquakes and their aftershocks, complicate the histogram as the cumulative daily aftershocks of the three events were compounded. This indicates that the aftershocks which are strong enough to be felt will persist for at most 2 months. Most felt events had been reported where the earthquakes are clustered west-southwest of Tulunan to Makilala and east of Kidapawan City to north of Mount Apo. Six (6) temporary seismic stations were also deployed to further constrain the locations of earthquakes in the area.



These isoseismal maps show the areas affected by varying levels of ground shaking during the 16 October 2019 M6.3, 29 October 2019 M6.6, and 31 October 2019 M6.5 events. The highest felt intensity was at PEIS VII (Destructive) for the M6.3 and M6.6 events; and PEIS VIII (Very Destructive) for the M6.5 event.

Impacts

- The municipal hall of Magsaysay, Davao del Sur suffered extensive damage during the October 16 M6.3 event which progressed to total damage without collapse during the October 31 M6.5 event.
- Completely damaged building with totally collapsed 1st floor. Other buildings in the area sustained slight to severe damage only.
- Tension cracks that indicate imminent landslides were observed in Brgy. Malailla, Makilala, Cotabato.
- Use of alternative substandard timber materials for posts and beams resulted in damaged houses and other structures.
- Earthquake-induced landslides in Brgy. Kononan, Kidapawan City that buried and severed off houses along its path and placed other upland houses at risk of further landslides.
- Heavily damaged typical concrete hollow blocks (CHB) houses due to poor construction and use of substandard materials.
- Numerous landslides in the mountains of Makilala, Cotabato.
- (Main photo) Lateral spreading in Brgy. Guiling, Hagonoy, Davao del Sur. (Inset) Sand fissures and fountaining (the height of which is demonstrated by the LORAN Officer in Brgy. Aringay, Kabacan, Cotabato).
- Liquefaction manifested by lateral spreading in Brgy. Ayalaya, Hagonoy, Davao del Sur. The maximum lateral separation increased after the October 31 M6.5 earthquake.
- Displaced families taking refuge in makeshift tents in the evacuation areas.
- Totally collapsed houses and extensive large tension cracks in Sibila, Laldagan, Upper Bala, Magsaysay, Davao del Sur prompted the QRT to recommend the immediate evacuation and relocation of all residents after the M6.3 event.

Summary of Geologic Impacts and Structural Damages

Public Engagements

DOST-PHIVOLCS QRT conducted information dissemination activities to explain the earthquake event to the people and allay their fears. Interviews with the media, as well as briefings with LGUs and private companies, were also conducted to provide updates and discuss recommendations based on the team's findings.

- ### Recommendations
- In case of another felt earthquake, do the "Duck/Drop, Cover and Hold."
 - Damaged buildings and infrastructures should be inspected by engineers after the last event (M6.5) and should not be used unless assessed as safe.
 - For areas with existing tension cracks, conduct pre-emptive evacuation, and be watchful of possible landslides triggered by earthquakes or prolonged heavy rainfall.
 - Formally train local masons and carpenters on the proper construction practice and use of standard construction materials. Reconstruction or construction of houses and buildings should conform with the National Building Code of the Philippines.
 - Strengthen the implementation of and compliance to the National Structural and National Building Codes of the Philippines.
 - Review and formulation of policies and ordinances that will address the gaps in the issuance of building permits and monitoring of building constructions.
 - National and local government units in collaboration with non-government agencies should provide psychosocial support such as stress-debriefing to affected communities.



The October 2019 Cotabato Earthquake Sequence

DOST-PHIVOLCS Quick Response Team


Seismicity Map from 16 October to 5 November 2019, 3pm

Epicenters

- A. M6.3 – Oct. 16, 2019
- B. M6.6 – Oct. 29, 2019
- C. M6.1 – Oct. 29, 2019
- D. M6.5 – Oct. 31, 2019

Cotabato Fault System

1. M'lang Fault
2. Makilala Fault
3. Balabag Fault
4. Makilala-Malungon Fault
5. North Columbio Fault
6. South Columbio Fault




- Epicenters**
- 09 July 2019 Event
 - ★ Magnitude 5.6
 - 16 October 2019 Events
 - ★ Magnitude 6.3
 - ★ Magnitude 5.5
 - 29 October 2019 Events
 - ★ Magnitude 6.6
 - ★ Magnitude 6.1
 - 31 October 2019 Event
 - ★ Magnitude 6.5

- Earthquake plots (AO 12-Nov-2019, 7AM)**
- 1.0 - 2.0
 - 2.1 - 3.0
 - 3.1 - 4.0
 - 4.1 - 5.0
 - 5.1 - 6.0

- Seismic Stations**
- ▲ Temporary
 - ▲ Permanent

- Active Faults**
- Solid Line - trace is certain
 - - - Dashed Line - trace is approximate
 - ┌┐┌ Hachures on solid line indicate downthrown area - trace is certain
 - ┆┆┆ Arrows on dashed line indicate side of flexure scarp/warp - trace is approximate


- Potentially Active Faults**
- - - Dashed Line - trace is approximate
 - ┌┐┌ Hachures on solid line indicate downthrown area - trace is certain





- # FOCAL MECHANISM SOLUTIONS
- 16 October 2019
 - Ms 6.3
 - 29 October 2019
 - Ms 6.6
 - 29 October 2019
 - Ms 6.1
 - 31 October 2019
 - Ms 6.5



The DinSAR map shows pattern of asymmetric fringes with a discontinuity oriented NW-SE which could possibly indicate the surface expression of the causative fault of the 16 October 2019 earthquake event. A net displacement of approximately 12 cm is observed.



Phase Map of the 16 October 2019 M6.3 North Cotabato Earthquake



Coordinate System: GCS WGS 1984
Datum: WGS 1984
Units: Degree

LOS Range

FD Azimuth

Acquisition Dates: 14 October 2019 (Pre-event)
26 October 2019 (Post-event)


Processing software: ISCE

Filters: Topography;
Power spectrum phase filtering;
Ionospheric filtering;
Low coherence masking


Data Source: Sentinel 1A, ESA;
SRTM, NASA-JPL; Prov. Boundaries, PSA;
Active Faults and Focal Mechanism, PHIVOLCS



The Line Of Sight (LOS) map shows a discontinuity oriented NW-SE which could possibly indicate the surface expression of the causative fault of the 16 October 2019 earthquake event. A LOS displacement of approximately 12 cm is observed. The blue shade indicates movement away from the satellite and the red shade indicates movement towards the satellite.




Line Of Sight Map of the 16 October 2019 M6.3 North Cotabato Earthquake



★ Epicenter

Coordinate System: GCS WGS 1984
Datum: WGS 1984
Units: Degree



Acquisition Dates: 14 October 2019 (Pre-event)
26 October 2019 (Post-event)


Processing software: ISCE

Filters: Topography;
Power spectrum phase filtering;
Ionospheric filtering;
Low coherence masking



Data Source: Sentinel 1A, ESA;
SRTM, NASA-JPL; Prov. Boundaries, PSA;
Active Faults and Focal Mechanism, PHIVOLCS



The Line Of Sight (LOS) map shows a discontinuity oriented NE-SW which could possibly indicate the surface expression of the causative fault of the 29-31 October 2019 earthquake event. A LOS displacement of approximately 40 cm is observed. The blue shade indicates movement away from the satellite and the red shade indicates movement towards the satellite.




Line Of Sight Map of the 29-31 October 2019 Cotabato Earthquake Sequence



★ Epicenter

Coordinate System: GCS WGS 1984
Datum: WGS 1984
Units: Degree



Acquisition Dates: 26 October 2019 (Pre-event)
07 November 2019 (Post-event)

Processing software: ISCE

Filters: Topography;
Power spectrum phase filtering;
Ionospheric filtering;
Low coherence masking

Data Source: Sentinel 1A, ESA;
SRTM, NASA-JPL; Prov. Boundaries, PSA;
Active Faults and Focal Mechanism, PHIVOLCS



The October 2019 Cotabato Earthquake Sequence


Plotted earthquakes as of 04:00 PM (PST)
28 October 2019

Recorded: 900


Plotted: 478

Felt: 56

Magnitude Range: 1.5 – 5.5




Recorded, Located and Felt	14	9	7	6	7	5	2	2	1	0	0	3
Recorded and Located	116	107	58	6	49	23	20	12	11	9	6	3
Recorded	230	67	12	38	20	7	8	5	5	2	13	14
TOTAL	360	183	77	50	76	35	30	19	17	11	19	20



The October 2019 Cotabato Earthquake Sequence

Plotted Earthquakes as
of 02 December 2019
12:00AM


Recorded	3890
Plotted	1705
Felt	246
Mag. Range	1.4-5.0
Ref. Station	PICP



The October 2019 Cotabato Earthquake Sequence


as of 12:00AM
December 02, 2019

Recorded	3890
Plotted	1705
Felt	246
Mag. Range	1.4-5.0
Ref. Station	PICP




After the 31 October 2019
M6.5

Recorded	2232
Plotted	895
Felt	96
Mag. Range	1.4-5.0
Ref. Station	PICP



29 October 2019 M6.6 Tulunan, Cotabato Earthquakes




M6.3
16 October

M6.6
29 October

M6.5
31 October


Magnitude-Time Graph



Ground motion modelling result for the M6.5 event vs. actual ground motion

SWIFT Centroid Moment Tensor Solution:

Input




Moment magnitude (M_w) = 6.5

Seismic moment (M_0) = 7.30×10^{18} Nm

(Lon, Lat, Depth) = (125.10°E, 6.80°N, 5 km)


(Strike 1, Dip 1, Rake 1) = (228°, 50°, -167°)

(Strike 2, Dip 2, Rake 2) = (129°, 80°, -41°)




PGA on rocksite

- 0.003 - 0.1
- 0.1 - 0.25
- 0.25 - 0.4
- 0.4 - 1.27




16 October 2019 M6.3



29 October 2019 M6.6







Earthquake Intensity based on PHIVOLCS Earthquake Intensity Scale (PEIS)	Province	City/Municipality
Intensity VIII (Very Destructive)	Cotabato	Brgy. Ilomavis, Brgy. Perez, and Brgy. Balabag in Kidapawan City
		Steep mountainous areas in Brgy. Buhay, Brgy. Batasan, Brgy. Malasila, Brgy. Sto. Nino, Brgy. Kisante, Brgy. Malabuan, Brgy. Luayon, Brgy. Bato, Brgy. Mabuhay, Brgy. Upper Indangan, Brgy. Buena Vida, Brgy. Malongon in Makilala; Purok 1, Brgy. Daig in Tulunan
Intensity VII (Destructive)	Davao del Sur	Ridge crests and steep slopes in So. Bandera, Brgy. Balabag, and Brgy. Kapatagan in Digos City
	Davao del Sur	Matanao, Magsaysay, Hagonoy, Digos City, Sulop, Padada, Bansalan, Magsaysay
Intensity VI (Very Strong)	Cotabato	Magpet, Tulunan, the rest of Kidapawan City and Makilala
	Cotabato	Tulunan, M'lang
	Davao del Sur	Sta. Cruz
	Independent/Chartered Cities	Davao City

31 October 2019 M6.5

Mapped earthquake impacts after the M6.3 (16 October 2019) event




M'lang, Cotabato




Damaged SB Hall in M'lang, Cotabato



Totally collapsed wall of a house in Brgy. Bagontapay, M'lang (lumber post were installed post-shaking to prevent total collapse of the roof)




Purok 8, Brgy. Lipaga, M'lang, Cotabato




Lateral spread and sandboil

Purok 8, Brgy. Lipaga, M'lang, Cotabato



Linear crack formed dividing the basketball court with occurrence of sandboils

Sitio Labidangan, Brgy. Upper Bala, Magsaysay, Cotabato




Out of 74 houses (wooden and semi-concrete houses), 25 houses were totally damaged and 36 heavily damaged because of poor construction and was affected by tension cracks.



Sitio Labidangan, Brgy. Upper Bala, Magsaysay, Cotabato




Purok Venus, Brgy. Managa, Bansalan, Davao del Sur



Shallow-seated landslide crown is approx. 8 m away from the national road with presence tension cracks.




Purok Venus, Brgy. Managa, Bansalan, Davao del Sur



Earthquake Impacts – Summary

Province	Municipality	Landslides	Tension Cracks	Liquefaction	Damages
		No. of Barangays Affected			
Cotabato	Kidapawan City	1			
	Alamada				1
	Aleosan				1
	Antipas	1			
	Arakan	1			
	Kabacan			2	1
	Makilala	11	2	1	12
	M'Lang	1	1	2	3
	Magsaysay	3	1		6
	Midsayap				1
	Pikit			3	1
Davao Del Sur	Tulunán	2	1		2
	Digos City				1
	Bansalan	4	3		3
	Hagonoy			1	
	Matanao	2	1	2	4



16 October 2019 M6.3 Tulunan, Cotabato Earthquake



Location: 23 km S62°E of Tulunan, Cotabato (9 km depth)



Magsaysay Municipal Hall



Brgy. Paraiso Birthing Hall



29 October 2019 M6.6 Tulunan, Cotabato Earthquake



Location: 22 km S79°E of Tulunan, Cotabato (7 km depth)



Magsaysay Municipal Hall



Brgy. Paraiso Birthing Hall



Earthquake Impacts: Ground Shaking



Eva's Building before the earthquakes. (Photo © 2019 Google, taken March 2016)



Eva's Building damaged during the October 31 2019 M6.5 event. Photo by the PHIVOLCS QRT (10312019)

Earthquake Impacts: Damaged buildings



Daig Elementary School, Tulunan, Cotabato



Earthquake Impacts: Damaged buildings



Makilala DRRMO after the 16 October 2019 M6.3 (left) and 29 October 2019 M6.6 (right) earthquakes

Earthquake Impacts: Ground Shaking



Totally collapsed house in Brgy. Sto. Nino, Makilala



Totally collapsed house in Brgy. Kisante, Makilala

Earthquake Impacts: Ground Shaking



Major damage with collapsed CHB wall in mixed-material house in Brgy. Asinan, Matanao



Completely collapsed CHB house that was constructed on a steep area in Brgy. Asinan. Tension cracks were also observed in front of this house.

Earthquake Impacts: Ground Shaking



A structure that was not damaged by the recent earthquakes



Wooden house built near the liquefied area in Poblacion, Matanao was able to withstand both the M6.6 and M6.5 quakes

Earthquake Impacts: Liquefaction



Lateral spread that appeared in Brgy. Tamlangon after the M6.6 earthquake that has worsened after the M6.5 earthquake



Sandboils observed in Brgy. Tamlangon after the M6.6 earthquake

Earthquake Impacts: Liquefaction

Lateral spreading in
Brgy. Aplaya, Hagonoy,
Davao del Sur



M6.3 (16 Oct. 2019)



M6.5 (31 Oct. 2019)

Earthquake Impacts: Damaged roads



These segments of the national road in Brgy. Kisante, Makilala, Cotabato were damaged after the M6.5 event



Earthquake Impacts: Earthquake-induced landslides



Landslide in Brgy. Bato and Malabuan
(photo from aerial survey; 10312019)



Landslide in Brgy. Buhay, Makilala



Landslide in Brgy. Bato and Malabuan
(photo from drone survey, 10312019)

COTABATO FAULT SYSTEM EARTHQUAKE GEOHAZARDS

Legend

Earthquake-Induced Landslide (EIL)


- EIL Survey Points
- EIL Oct. 16 Event
- EIL Oct. 29/31 Event

Liquefaction

- Liquefaction Survey Points
- Liquefaction

Administrative Boundary

- Municipal Boundary



Legend

Earthquake-Induced Landslide (EIL)

- EIL Survey Points
- EIL Oct. 16 Event
- EIL Oct. 29/31 Event

Liquefaction

- Liquefaction Survey Points
- Liquefaction Inventory

Administrative Boundary

- Municipal Boundary



DATA SOURCES:

- Sentinel-2B Imagery © ESA (2019), 08 November 2019
- Administrative boundary from PSA, 2016
- Earthquake-Induced Landslide and Liquefaction Delineation based from PHIVOLCS-Quick Response Team, 2019

MAP PRODUCED BY:

Department of Science and Technology - Philippine Institute of Volcanology and Seismology (DOST-PHIVOLCS), November 2019





Legend

Earthquake-Induced Landslide (EIL)



- EIL Survey Points
- EIL Oct. 16 Event
- EIL Oct. 29/31 Event

Liquefaction

- Liquefaction Survey Points
- Liquefaction


Administrative Boundary

- Municipal Boundary



From DOST-ASTI (Makilala and Kidapawan City)





Legend

■ Potential Landslide Areas

POTENTIAL LANDSLIDE AREAS


Kidapawan City and Makilala, Cotabato as of 15 November 2019

Map Information

This map shows the areas potentially affected by earthquake-induced landslides in Kidapawan City and Makilala, Cotabato. The DATOS Team used its AI models to predict the baresoil and vegetation cover from Planetscope satellite images. Areas with changes from vegetation to baresoil are interpreted as potential landslide areas.

Cartographic Information

Coordinate System: WGS 84/UTM Zone 51N



Data Sources

Planet images captured on 11/09/2019 and 11/15/2019, provided by the PEDRO Center.



The October 2019 Cotabato Earthquake Sequence
DOST-PHIVOLCS Quick Response Team

Recommendations

Evacuation and/or Relocation of the following due to landslide threat:

Makilala, Cotabato

1. Bgy. Bato
2. Bgy. Buhay
3. Bgy. Cabilao
4. Bgy. Luayon
5. Bgy. Sto Niño (Purok 1 & 2)
6. Bgy. Malabuan (Purok 12 and Sitio Basak)
7. Bgy. Poblacion (Purok Malaang)
8. Bgy. Malungon (Purok 2 & 7)

Tulunan, Cotabato

1. Bgy. Daig (Purok 1 / Center)
2. Bgy. Bacong (selected houses near Bgy. Hall)



Taken by PHIVOLCS QRT
at Bgy. Luayon, Makilala



Drone photo taken by
PHIVOLCS QRT at Bgy. Daig,
Tulunan

Recommendations

Evacuation and/or Relocation of the following due to landslide threat:

M'Lang, Cotabato

Bgy. New Esperanza
(Sitio Byao)

Bansalan, Davao del Sur

1. Bgy. Altavista (Sitio Sunop)
2. Bgy. Managa (Purok Pananag B)
3. Bgy. Anonang (Sitio Malupo)

Magsaysay, Davao del Sur

1. Bgy. Upper Bala (Sitio Labidangan)
2. Bgy. Malawanit (Purok 6)

Kidapawan City

Bgy. Ilomavis (Sitio Agco)



Drone shot in Purok Pananag B,
Bgy. Managa, Bansalan




Landslide in Bgy.
Malawanit, Magsaysay

Recommendations

Earthquake-Related Hazard Assessment of 45 Proposed Relocation Sites in Cotabato

1. Kidapawan City (13 sites)
 2. Makilala (16 sites)
 3. Tulumán (15 sites)
 4. M'lang (1 site)
- (as of 10 November 2019)



HIM-Nov-19-109

11 November 2019

EMMYLOU TALIÑO-MENDOZA
Acting Governor
Cotabato Province

Dear **Honorable TALIÑO-MENDOZA**:

This pertains to your request for earthquake-related hazard assessment for the forty-five (45) proposed relocation sites for communities affected by the recent earthquakes in Cotabato Province. We are pleased to provide you the hazards assessment (in table format), including the explanations of hazard impacts and recommended actions for prevention and mitigation.

Out of the 45 sites, 37 were assessed by DOST-PHIVOLCS Quick Response Team together with DENR-Mines and Geoscience Bureau (MGB), National Housing Authority, and the LGUs. Eight (8) sites were evaluated by DENR-MGB alone. All sites will be further evaluated upon receipt of polygon-based locations.

In addition, we have attached herewith the assessment maps showing the proposed relocation sites relative to the nearest active faults in the area, for your reference. We have also included the latest Earthquake Information Primer, for your perusal. For quick conduct of hazards assessment in the future, visualization of hazards and monitoring of earthquake events, please access <https://hazardhunter.georisk.gov.ph>.

We hope to have provided you with the necessary information. Please do not hesitate to contact our office should you need further information or assistance.

Very truly yours,


RENATO U. SOLIDUM, JR.
Undersecretary, DOST
and
Officer-in-Charge, PHIVOLCS

Recommendations


1. Houses and buildings, especially those with damages, should be inspected if these are still resistant to a strong shaking; those that were not damaged should be assessed if they followed the building code and can resist strong shaking; LGUs and engineering organizations should have these inspected.
2. Public should review their earthquake preparedness response during and after shaking.
3. Areas that are highly susceptible to landslides, especially those that were affected by landslides or those with tension cracks, should be avoided or vacated as strong shaking or prolonged rainfall may cause these slopes to slide.
4. Formally train local masons and carpenters on the proper construction practice and use of standard construction materials. Reconstruction or construction of houses and buildings should conform with the National Building Code of the Philippines.




The October 2019 Cotabato Earthquake Sequence: Parameters and impacts




Cotabato Fault System



Bukidnon and Cotabato Active Faults



Bukidnon Active Faults



Davao Del Sur Active Faults