

The September 2018 Naga landslide: Analysis and lessons learned

Nathan Azriel S. Veracruz^{1,2*}, Sandra G. Catane¹, John Romel R. Flora¹,
Chatty Mae M. Go¹, Rochelle E. Enrera¹, and Erizza Rose U. Santos^{1,2}

¹Engineering Geology Laboratory, National Institute of Geological Sciences, University of the Philippines Diliman

²Philippine Institute of Volcanology and Seismology, Department of Science and Technology

*Corresponding author: nasveracruz@gmail.com

- 20 September 2018, 05:53 AM
- Brgy. Tinaan, Naga City, Cebu
- 77 dead, 7 injured, 57 damaged houses, 8,252 people affected (NDRRMC, 2018)
- Affected barangays Mainit, Inoburan, Naalad, and Tinaan (including sitios Sindulan and Tagaytay)
- Damming in Pandan River
- Tension cracks reported at least 3 weeks before the landslide






- Lasted for 67 s
- Landslide moved en masse and then split into two major directions

Frames from the CCTV footage of BJMP

Pre-failure deformation


- 2007: intermittent ground cracks and rockfalls
- 2016: small tension cracks



Tension cracks	Orientation	29 August 2018			18 September 2018			Mean net HD (cm)	Deformation rate (cm/day)
		L (m)	HD (cm)	VD (cm)	L (m)	HD (cm)	VD (cm)		
T1	35°, 80° SE	45	8–10	~ 0	Increased	19–19.5	11–11.5	10.25	0.51
T1-W	10-20°, 90°	1–1.5	1–3	~ 0	18–19	16–17	Not reported	14.5	0.73
T1-SE	NW strike	1–1.5	< 1–3	~ 0	Not reported			–	–
T1-N	35°, 90°	Not reported			> 50	19–19.5	24–25	19.25	–
T2a, T2b, T2c	10-65°, 90°	1–1.5	3–6	~ 0	Increased	14–14.5	3–6	9.75	0.49

Pre-failure deformation


- Predominantly NE-trending cracks
- Progressive widening of cracks → tensional failure → shear strength reduction



Tension cracks	Orientation	29 August 2018			18 September 2018			Mean net HD (cm)	Deformation rate (cm/day)
		L (m)	HD (cm)	VD (cm)	L (m)	HD (cm)	VD (cm)		
T1	35°, 80° SE	45	8–10	~ 0	Increased	19–19.5	11–11.5	10.25	0.51
T1-W	10-20°, 90°	1–1.5	1–3	~ 0	18–19	16–17	Not reported	14.5	0.73
T1-SE	NW strike	1–1.5	< 1–3	~ 0	Not reported			–	–
T1-N	35°, 90°	Not reported			> 50	19–19.5	24–25	19.25	–
T2a, T2b, T2c	10-65°, 90°	1–1.5	3–6	~ 0	Increased	14–14.5	3–6	9.75	0.49

General description of the landslide



- Area: $\sim 9.5 \times 10^5 \text{ m}^2$ ($\sim 95 \text{ ha}$)
- Volume: $\sim 27 \text{ M m}^3$
- Velocity: 0.63–7.91 m/s (very rapid to extremely rapid)
- Runout: 1.34 km
- Head scarp: 480-m-long, $\sim 50\text{-m}$ -high, $55\text{--}75^\circ$ steep
- Underlain by limestones of the Plio-Pleistocene Carcar Formation
 - Thinly to thickly bedded calcarenites and calcirudites
 - Gently SE-dipping (low-angle) and daylighting
 - Poorly cemented and very porous



Post-landslide orthomosaic from Ariel Lazarte


Mechanism: evidence from deposits

- Successive detachment of multiple blocks along a series of tension cracks
- Primary and secondary tension fractures
- Slab-like and wedge-like blocks
- Landslide deposit facies: intact blocks, fragmented blocks, dry flow deposits, rockfall deposits, collapsed blocks → variable processes within a single landslide
- Most blocks retained their upright positions → predominant translational mechanism



Mechanism: evidence from deposits

- Successive detachment of multiple blocks along a series of tension cracks
- Primary and secondary tension fractures
- Slab-like and wedge-like blocks
- Landslide deposit facies: intact blocks, fragmented blocks, dry flow deposits, rockfall deposits, collapsed blocks → variable processes within a single landslide
- Most blocks retained their upright positions → predominant translational mechanism



How does the 2018 Naga landslide fare against the 2006 Guinsaugon landslide?




2006 Guinsaugon



2018 Naga

	2006 Guinsaugon (Catane et al., 2007, 2008)	2018 Naga
Area	3.2 km ²	9.5 km ²
Volume	14–18 M m ³	27 M m ³
Maximum velocity	120–130 m/s	7.9 m/s
Runout	4.1 km	1.34 km
Mechanism	rockslide-debris avalanche	translational block slide


What could have triggered the landslide?



Rainfall data from DOST-ASTI rain gauge located 900 m NW of the landslide


- 15 September: Typhoon Ompong made landfall in Cagayan about 900 km NNW of Naga City
- 17 September: 30 mm maximum daily rainfall
- 20 September, 04:00-05:45 AM: 4.5 mm instantaneous rainfall
- 1-20 September: 99.5 mm cumulative rainfall
- Far below the global threshold of 100 mm/day
- Rainfall is unlikely to have triggered the landslide

What could have triggered the landslide?




- 26 February 2018, 06:36 AM
 - Ms 3.0 shallow (32 km) earthquake about 2.8 km SW of the landslide
 - No reports of earthquake intensity and landslide precursors
- No earthquakes immediately prior or during the landslide
- 21 October 2018, 07:04 PM
 - Ms 3.4 shallow (10 km) earthquake about 1.8 km SW of the landslide
 - PEIS IV was reported
 - No reports of landslide reactivation
- Earthquake is unlikely to have triggered the landslide

What could have triggered the landslide?




- Steep cut slopes associated with extraction activities
 - Change the load distribution on potential slip surfaces
 - Change the hydrologic conditions of the slope
 - Expose potential slip surfaces
 - Withdraw support at the toe
- Investigate the effect of cut slopes through probabilistic slope stability analyses

Preliminary slope stability analyses



- 2D limit equilibrium analyses
 - Daylighting bedding planes as potential slip surfaces
 - Assumptions: homogenous material, unsaturated condition
 - Estimated material strength parameters:
 - Unit weight = 17–23 kN/m³
 - Intact UCS = 5–25 MPa
 - GSI = 36–54
 - Intact rock constant = 5–15
 - Disturbance factor = 1.0

Preliminary slope stability analyses



- 2D limit equilibrium analyses
 - Factors of safety:
 - (a) 0.969–3.96
 - (b) 0.668–2.798
- Slopes may already be marginally stable
- Additional removal of support by extraction activities → increase in shear stress
- Further exposure of potential slip surfaces from cut slopes → decrease in shear strength

Conclusions

- The September 2018 Naga landslide is a low-angle translational block slide
- Rainfall and earthquake are unlikely to have triggered the landslide
- Cut slopes were marginally stable along a low-angle slip surface even at unsaturated conditions
- There is no immediate direct trigger to the landslide
- Eventual failure can be due to progressive weakening of the slope or further disturbance of the slope

Lessons learned

- Development of tension cracks at least 3 weeks before the landslide provided reasonable lead time to issue an early warning
- This prompted the timely evacuation of the residents of Tagaytay, where the tension cracks were located
- However, most of the casualties came from Sindulan and Naalad at the distal end of the landslide because of the lack of information on potential landslide runout
- There should have been fewer casualties if the volume and runout were anticipated
- Modelling of possible landslide runout must be part of any landslide investigation



Lessons learned

- Review cut slope designs and extraction methods
- In any extraction activities, full-time monitoring by geologists and geotechnical engineers is essential



Thank you!
